



Gate in field ditch

Clark Moulton Property

Mormon Row Historic District

GRTE Tetun CO way

HRA 1995

Neg: NPS Denver CO

View to W

photo # 96

96

31



T.A. Moulton Barn #1324

Norman Row Historic District

CRTE Teton Co WY

NRH 1995

Neg: NPS RMSSO Denver CO

View to NE

photo #97

97 32



T.A. Moulton Barn (~~112~~ 1324)

Norman Row Historic District

CRTE Teton Co WY

HRA 1995

Neg: NPS RMSSO Denver CO

View to E

photo #98

98 33



Barn # 1324

T. D. Moulton Property

Thormen Row Historic District

GRTS Tetun CO WY

HRA 1995

Neg: NPS, Denver CO

View to W. South shed-roof component -
interior

photo #99

99 34



Barn # 1324 = 1324

100
35

T.A. MOULTON Property

Norman Row H.P.

CRTE Teton Co, WY

HRA 1995

Neg: NPS Denver CO

Interior
Detail of stall partition, view
to ~~west~~ west

photo #100

100

35



Barn # 1324

T.A. Mountain Property

Norman Row Historic District

GRTE Teton CO, WY

HRA 1995

Neg: NPS Denver CO

View to SE, interior central (original)
component

photo #101

101 36



Concrete housing for head gate (S-3)

T.A. Moulton property

Mormon Row Historic District

GRTE, Teton Co., WY

HQA 1995

Req: NPS RmSSO Denver Co

View to: WNW

photo #102

102 38



Acadgate (S-1) + field ditch

T. A. Moulton property

Mormon Row H.D.

CRTE Tetra Co, WI

WRA 1995

Neg: MRS Rmsso Denver
CO.

View to W

photo # 103

103

39



Overview

T.A. Moulton Homesite, from barn

Mormon Row Historic District

CRTE Teton Co. WY

HRA 1995

req: NPS RMSSO, Denver

View to SE

photo #104

1040



Overview of homsite from Mormon Row Road
John Moulton Property and ditch

Mormon Row N.D.

CARTE Tetra Co., WY

HRA 1995

neg: NPS RMSSO Denver

View to NW

photo # 105



Bankhouse ¹²⁸⁰ + Residence # 1276

John Mountain Property

Thorman Row Hill

ARTE Teton CO WY

HRA 1994

Neg: NPS, Denver CO

View to NW

photo #106

106 42



Residence → 1276

John Moulton Property

Thorne Row Historic District

CRTE Teton CO WY

HRA 1995

neg: NPS Denver CO.

View to W

photo # 107

107 43



Residence #1278

John Moulton Property

Norman Row Historic District

GRTE Teton Co. WY

HRA 1995

Neg: NPS, Denver CO

View to S

photo #108



Residence #1276

John Shoulton Property

Thorman Row Historic District

C.R.T.E. Teton CO, WY

HRA 1995

Neg: NPS, Denver, CO.

View to E

photo #109

109 45



Residence # 1276

J. Moulton Property

Mormon Row Historic District

GRTE Tetun Co. WY

HRA 1995

Neg: NPS Denver Co.

Interior, mud room. View to S

photo # 110



Residence #1276

J. Moulton Property

Thorman Row H.D.

GRTZ, Teton Co. WY

ARA 1995

Neg: NPS, Denver CO

View to S KITCHEN INTERIOR

photo # 111

111 47



Residence #1276

J. Moulton Property

Mormin Row H.P.

CRTE Teton CO, WY

HRA 1995

Neg: NPS Denver CO

View to ESE. Interior, NW
bedroom.

211

photo # 112

112
48



Outhouses (1276A and 1276B)

John Moulton Property

Mormon Row Historic District

GRETE Tetun CO, WY

ARA 1995

Neg: NPS, Denver, CO

View to NE

photo #113

113 49



Outhouses (1276A and 1267B)

John Moulton Property

Morrison Row Historic District

GRTE Teton Co. WY

HRA 1995

Neq: NPS Denver, CO

View to SW

photo # 114

114 50



Barn #1278

John Moulton Property

Mormon Row Historic District


GRTE Teton CO WY

HEA 1995

neg: NPS, Denver CO

View to NE

photo # 115



Baru # 1278

John Mountain Property

Thorman Row Historic District

GRTE Teton CO WY

HRA 1995

Neg: NPS, Denver, CO.

View to W

photo # 116

116 52



Barn # 1278

John Moulton Property

Mormon Row Historic District

GRTE Tetun CO WY

ALA RAS

Neg. ~~NPS~~, Denver CO.

View to SE

photo # 117

117 53



Barn #1278

John Moulton Property

Mormon Row Historic District

GRTE Teton Co WY

HRA 1985

Reg: NPS Denver CO

View to: N.A. Notching detail,
gambrel shed junction

811

photo #118

118 54



Barn # 1278

119
55

J. Moulton Property

Norman Row Historic District

GRTE Teton Co WY

HRA 1995

Neg: NPS Denver CO

Interior, south end, view to E

photo # 119

119
55



Barn #1278

120
56

J. Moulton Property

Thomson Row H.D.

CRTE Tetun Co WY

HRA 1995

Neg: NPS Denver CO

Detail of steel partition

120 photo #120

56



Bunkhouse #1280

John Moulton Property

Mormon Row Historic District

CRTE Teton CO WY

HRA 1995

Neg: NPS Denver CO

View to SW

photo # 121

121

57



Bunkhouse # 1280

John Moulton Property

Thorman Row Historic District

GRTE Teton Co., WY

HRA 1995

Neg: NPS, Denver, CO

View to NE

photo # 122

122

58



Bunkhouse #1280

J. Moulton Property

Mormon Row H.D.

CRTE Teton Co. WY

HRA 1995

Neg: NPS, Denver CO

Detail of built-in hatch,

View to SW



Bunkhouse # 1280

J. Moulton Property

Thorman Row Historic District

CRTE Tetun Co WY

NRA 1995

Neg: NPS Denver Co.

Interior: Living Room Area. View to SE

photo # 124

124

60



Granary # 1281
John Moulton Property
Therman Row H.D.
GRTE Teton Co WY
HRA 1996
Neg: NPS Denver Co.
View to NW

photo # 125

125

61

